

Nitritex Ltd.

Company Registration No. 03231971 (England & Wales)
VAT No. GB 676 8083 88

Ground Floor,
15 Kings Court, Willie Snaith Road
Newmarket, Suffolk, CB8 7SG
United Kingdom

T. + 44 (0) 1638 663338
F. + 44 (0) 1638 668890
Info@nitritex.com
www.ansell.com

June 2023

Ref: LSCCN058

**Change Notification - BioClean™ coverall & garment design improvements
(S-BDCHT, BDCHT, S-BDFC, BDFC)**

Dear Valued Customer,

Following an announcement sent in December 2021 regarding launching new coverall design improvements to reduce the risk of contamination, improve fit and streamline production efficiency, we can confirm this has now been implemented to the following products from the lot numbers shown in Table 2 below:

Table 2

Product Styles	Lot number
BDCHT-S	22-2482
BDCHT-M	22-2485
BDCHT-L	22-2486
BDCHT-2XL	22-2488
BDCHT-4XL	23-0335
S-BDCHT-S	22-2481
S-BDCHT-M	22-2483
S-BDCHT-L	22-2473
S-BDCHT-2XL	22-2487
BDFC-M	23-0417
BDFC-L	22-2406
BDFC-XL	23-0418
BDFC-2XL	22-2333
BDFC-4XL	23-0415
S-BDFC-M	22-2329
S-BDFC-L	22-2437
S-BDFC-XL	22-2330
S-BDFC-2XL	22-2331
S-BDFC-3XL	22-2408
S-BDFC-4XL	22-2332

In addition to the improvement features-outlined in the previous announcement, the sole of the Overboots on the S-BDFC and BDFC coverall have been improved with laminated soles, instead of material thread stitched onto the sole, to help keep the surface cleaner and reduce risk of particle contamination. This change will be implemented from the lot numbers listed in Table 2.

Before and after images of S-BDFC/BDFC Overboots soles can be seen below:



Should you have any questions regarding any items covered by this announcement please contact your local Ansell Nitritex customer service or sales representative.

Thank you for your continued loyalty and support.

Yours faithfully,

François le Jeune

Chief Commercial Officer
EMEA/APAC

Martijn Spaans

Director Sales, Life Sciences Solutions
EMEA/APAC

